


ISPM 15 (WPM) Marking Requirements

1. Examples of acceptable marks



2. Examples of unacceptable marks

No.	Unacceptable Mark	Reason for rejection
2.1	ZA-A39 HT - DB	IPPC logo outside the leaf.
2.3		Illegible
	A The second sec	IPPC logo and the leaf on the wrong side of
	101 PF .	the mark
2.4		Incorrect shape, round instead of square or
	TZS HT	rectangular

2.5



 Additional information within the borders of the mark

2.6



 Illegible, incomplete, hand drawn and no border line separating logo from country information

Mark should be:

- a. Registered with DAFF-DIS.
- b. Legible, permanent and not transferable.
- c. Placed in visible location, preferable on at least two opposite sides.
- d. Rectangular or square in shape.
- e. Surrounded by border line with a vertical line separating IPPC logo from country information.
- f. Stencilling mark: small gaps may be present in the border, vertical line and elsewhere among the components of the
- g. Must not be hand drawn.
- h. No other information shall be contained within the borders of the mark.
- i. No variations in the symbol/mark should be accepted.
- j. As traceability requirements dates must be included on certified wood packaging material to correspond with records however it must strictly be outside the borders of the mark.
- k. "DB" is no longer a requirement
- I. The mark should consist of:
 - The symbol IPPC logo
 - Country code ZA
 - Unique code allocated to service provider
 - Treatment code MB /HT